THIS PAGE IS INSERTED BY OIPE SCANNING AND IS NOT PART OF THE OFFICIAL RECORD

Best Available Images

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

BLACK BORDERS

TEXT CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT

BLURRY OR ILLEGIBLE TEXT


SKEWED/SLANTED IMAGES

COLORED PHOTOS HAVE BEEN RENDERED INTO BLACK AND WHITE

VERY DARK BLACK AND WHITE PHOTOS

UNDECIPHERABLE GRAY SCALE DOCUMENTS

IMAGES ARE THE BEST AVAILABLE COPY. AS RESCANNING WILL NOT CORRECT IMAGES, PLEASE DO NOT REPORT THE IMAGES TO THE PROBLEM IMAGE BOX.









FIG. 2





and the state of t

FIG. 4



F16.5





FIG. GA



F16. 6B

P


N

• M

• N'


P

FIG. 7A



F16. 7B


5000



A Generic Oil Based Mud Imager

(d) 514

800 m






FIG. 10





FIG. IL

FIG. 12






FIG. 13





FIG. 14









FIG. 16





F16.19



Measure resisherly at second 2102

Measure resisherly at second 2102

depth into bornation

Determining the presence/

magnitude of a standoff 12103

from a borhole wall for

a resishiry tool